

University of Wisconsin Stevens Point

GIS as a Tool for Mapping Shoreline Health



2014 Lakes Convention D. McFarlane, GIS Specialist Center for Land Use Education University of Wisconsin – Stevens Point






- Identify areas of shoreland that may need protection or restoration
- Provide a different perspective
- Develop a baseline for future comparison
- Provide specific information to property owners



Stevens Point

What is Health Shoreland Vegetation?

- A combination of native flowers and grasses/shrubs/trees
- Should extend at least 35 feet inland






Stevens Point

Portage County 2002 to 2012

- 21 lakes surveyed in both years
- Comparing "developed" and "undeveloped" shorelands:
 - 9 Improved by 400 to 4,800 feet
 - 2 Decreased by approx. 400 feet
 - 10 Remained about the same







Vegetation Survey

University of Wisconsin Stevens Point



Shore	line Ve	egetat	ion Su	irvey			
Lake Name:			Researche	ers:			
Date:		-					
Weather:	-						
Shoreline S							
Map ID or Waypoint Range							
Shorelin	e Vegetat	ion and Gr	ound Cond	itions			
Deminant Shoreline Cover Type (check one)	Width that y	e the UNMOW ou observe tha djacent to the	Buffer Density				
Mowed lawn			No Buffer*		Sparse		
Organic/Leaf pack (Undisturbed)			<1'		(30%)		
Barren/Dirt (Disturbed)			1-5'		Moderate		
Impervious Surface			5-15'		(30-70%)		
hort Unmowed Vegetation			15-35'		Dense		
New Shoreland Restoration			35-50'		(>70%)		
		>50'					
*Check this when Mowed Lawn, Barren/Dir the dominant shoreline cover type.	t, or Impervio	us Surface is s	elected as				
Tall	Shoreland	Vegetatio	n				
Are trees and shrubs present?	Present		Tre	ee/Shrub Den	sity		
Are trees and shrubs present:	Absent		Sparse	(<30%)			
				(30-70%)			
			Dense	(>70%)			
					I		
	Voody Stru		Descent				
Is woody habitat present in the v shoreline?	near the	Present Absent					
					-		
Shor	eland Slop	e					
Approximate slope of shore zo	Flat (<5%)	Moderate (5-15%)	Steep (>15%)				



Shoreland Alterations

University of Wisconsin Stevens Point

	S	horelir	ne Hum	ian Influe	ence	Sur	vey		
Lake Name:				Resea	rchers:		-		
Date:			-		_				
Weather:			-	GF	S Unit:				
			Shore	land Alterations	;				
	Map	Est.				Мар	Est.		
Feature Type	ID	Length (ft)	Condition	Feature T	ype	ID	Length (ft)	Condition	n
Artificial Beach			Poor Fair Good	Principle Structure				Poor Fair Good	
Boat Landing			Poor Fair Good	Principle Structure				Poor Fair Good	
Culvert		NA	Poor Fair Good	Other Stru 0-35'	icture			Poor Fair Good	
Dam/Spillway			Poor Fair Good	Other Stru 35-75'	icture		NA	Poor Fair Good	
Dock/Pier		NA	Poor Fair Good	Rip Rap				Poor Fair Good	
Erosion			Low Moderate Severe	Seawall				Poor Fair Good	

Shoreland Alterations												
Feature Type	Map ID	Est. Length (ft)	Condit	tion		Feature Type	Map ID	Est. Length (ft)	Condi	tion		
Artificial Beach			Poor Fair Good			Principle Structure 0-35'		NA	Poor Fair Good			
Boat Landing			Poor Fair Good			Principle Structure 35-75'		NA	Poor Fair Good	F		
Culvert		NA	Poor Fair Good			Other Structure 0-35'		NA	Poor Fair Good	F		
Dam/Spillway			Poor Fair Good			Other Structure 35-75'		NA	Poor Fair Good	F		
Dock/Pier		NA	Poor Fair Good	F		Rip Rap			Poor Fair Good			
Erosion			Low Moderate Severe			Seawall			Poor Fair Good			